Manager's Report

March 1, 2015

Buildings and Grounds

Cocciardi and Associates inspection report attached.

Infrastructure

Roads

Calcium Road Bridge remains closed. We have been notified that Lehigh Cement will begin using rail on a limited basis.

Bridges, Culverts, Storm Water –Drainage issues must still be corrected along Hill Road.

Escrow Releases: Meadowbrook – Release held.

Chestnut Street

PA DEP called to find out our progress on the storm water issues at the enclosed stream. They are closing the file but will issue us an emergency permit if and when the Township makes repairs. There has been no further action on the part of the homeowner in signing the easement agreement.

Planning

LTL has provided a quote on code enforcement services and building inspection services.

Zoning and SALDO revised drafts have been provided by SDE to Great Valley. I would like to suggest that the Board consider adopting the revisions.

We received notice that the FCC has received an application for a cell tower at 220 Buena Vista. I spoke with D. Zwicky and he said Verizon will be going through the planning process.

Zoning and Codes

- 358 W Walnut Tree Drive did not sell and may sit another year abandoned.
- 59 Bertolet Place has had some work completed but is not finished.
- 164 S View Road has been repaired and must be inspected by SDE.
- 115 Grove Road remains condemned DJ fine issued. Ongoing.

Commercial Properties requiring permit inspections/closeouts

- Micro Air Computer – business open, final inspection completed and c/o not completed.
- Maiers Grove Pavilion– failed final. Needs reinspection

Complaints – All are more than 90 days old and with SDE for resolution

- 405 Golden Drive – trash and junk in yard
- 217 Holiday Lane – swale filled in when driveway was paved
- 216 Holiday Lane - trash and junk in driveway, abandoned vehicle
- 205 Holiday Lane – house in disrepair
- 252 Main - trash and junk in yard
- 1370 Pleasant Hill Road – running car repair shop out of residential garage
- 100 Sunset Ave – weeds, trash, unlicensed motor vehicle in yard
- 432 E Wesner – fence higher than 6'
- 332 Cassidy Ct – swale not being maintained
- 357 Lindbergh Apt 17 – abandoned vehicles
- 102 Hill Road – unlicensed vehicles

Recycling

Yearly reporting is completed. The 902 Equipment Grant reimbursement has been received and deposited in the Operating Reserve Account. We need to purchase a stencil that indicates the mini ex and the truck were purchased through a grant provided by the PA DEP.

COCCIARDI
and Associates, Inc.
Safety • Environmental Health • Emergency Preparedness
Consulting and Training

February 19, 2015

Ms. Diane Hollenbach
Township Manager
Maidencreek Township
PO Box 319
1 Quarry Road
Blandon, PA 19510

RE: Maidencreek Township
Site Safety Inspection
Cocciardi Job #15-8020

Dear Ms. Hollenbach:

The following document is being provided to document the activities, findings, and recommendations relative to the supplemental site safety evaluation completed at the Maidencreek Township (MTWP), located in Blandon, Pennsylvania.

BACKGROUND:

Since 2004, Cocciardi and Associates, Inc. (Cocciardi) has been contracted by Housing and Redevelopment Insurance Exchange (HARIE) to provide site safety evaluations for existing workers' compensation policyholders at various municipality, redevelopment, sewer, and housing authority locations throughout the Commonwealth of Pennsylvania. The safety evaluations are designed to provide HARIE clientele with recommendations to improve employee safety through remediation of potential physical hazards and implementation of safety and health programs. Evaluations were performed in accordance with criteria, standards, and recommendations established by various regulatory agencies and applicable professional associations, including the Occupational Safety and Health Administration (OSHA), National Institute for Occupational Safety and Health (NIOSH), American National Standards Institute (ANSI), National Fire Protection Association (NFPA), etc.

The site safety compliance audit was completed for your organization on January 20, 2015. Reports summarizing associated findings and recommendations are provided below. The following document identifies specific deficiencies/potential hazards, associated locations, the standard/code identification relative to the deficiency, and recommended corrective actions for each deficiency or hazard.

This report is sub-divided into two sections:

Section 1: Administrative Review- Includes results of on-site interviews with pertinent personnel to identify general organization operations, site descriptions, workers' compensation injury/illness trends, and implemented safety programs. Additionally, response measures completed by the organization to address Cocciardi recommendations resulting from the previous site evaluation will be discussed, if applicable.

Section 2: Safety Survey Building-Wide Findings- Includes results of the walk-through inspection of all applicable facility buildings.

SECTION 1: ADMINISTRATIVE/SITE BACKGROUND INFORMATION

Cocciardi personnel, Mr. Jason Smith, (Safety, Health and Environmental Technologist), conducted the inspection on January 20, 2015. Included in the inspection was an interview with township personnel Ms. Diane Hollenbach. MTWP facilities included in this inspection comprised of the following:

1. Township Administrative Office
2. Road Crew Work Office Area
3. Road Crew Garages
4. Road Materials Storage Area
5. Material Storage Area/Garage

Personnel employed at the facility include (approximate):

Administrative:	2
Maintenance:	5

MTWP utilizes sub-contractors for various operations, including annual fire extinguisher inspections; boiler maintenance; Heating, Ventilating, and Air Conditioning (HVAC) maintenance; electrical; insect/pest control services; first aid kit inventory and supplies; etc. Minor electrical, boiler and HVAC repairs, general housekeeping, landscaping, snow removal and general maintenance are all conducted in-house. A certified Workplace Safety Committee has been created and established this month.

The following notifications should be posted in various areas employees have access to, including a panel list of physicians, and also post Worker Right-to-Know posters (attached).

Cocciardi recommends MTWP utilize programs available to implement and train staff on site specific safety programs applicable to facility operations, including:

- Hazard Communications/Employee Right-to-Know
- Electrical Safety and Lockout/Tagout
- Hearing Conservation Program
- Confined Spaces
- Respiratory Protection and Personal Protective Equipment
- Accident Investigation

SECTION 2: SITE FINDINGS/RECOMMENDATIONS:

Site findings, and associated code references, locations and recommendations, identified by the inspector(s) are summarized below.

FINDING #1: Employee Egress

Applicable Regulations/Codes

- OSHA: Means of Egress (29 CFR 1910 Subpart E)
- NFPA: Life Safety Code (NFPA 101)

Summary

Site/Building	Location	Finding Description	Recommendation
Administrative Building/Road Crew Area	Multiple locations	Non-illuminated Exit signs found in various locations.	Replace with illuminated or photoluminescent Emergency Exit signs.
Administrative Building/Road Crew Area	Meeting Room and Road Crew Garage	Emergency Exit was obstructed by items.	Remove any material blocking or impeding egress near exits or in exit pathways.
Road Crew Garage	Mezzanine Area	Emergency Lighting unserviceable	Install emergency lighting to allow people to see an exit during an emergency or power failure.
Administration Building	Hallways	Hallways do not indicate an emergency exit pathway.	Install emergency exit lights with direction path to indicate the way to the nearest emergency exit.

Site/Building	Location	Finding Description	Recommendation
Administration Building	Throughout	Doors in emergency exit pathways which are not exits not labeled "NOT AN EXIT" or identified by purpose.	Place "NOT AN EXIT" sign on any door in an emergency exit pathway or identify room's purpose.
Administration Building	Locker room hallway	No exit sign present to indicate the emergency exit and stair tower allows access to lower level.	Install Emergency Exit sign indicating egress to the parking lot. Place a barrier, such as a swinging gate or chain that prevents a person from getting confused or lost by not using the designated emergency exit or indicate additional lower level emergency exit.
Administration Building	Women's & Men's Restroom/Road Crew South Garage	Work areas do not have Emergency exits or Emergency lighting.	Install Emergency Exit signs or emergency lighting to allow people to see an exit during an emergency or power failure.
Storage Area/Garages	Utility Room in rear Hallway, West Garage/Storage Area, Exterior Garage	Work areas do not have Emergency exits or Emergency lighting.	Install Emergency Exit signs or emergency lighting to allow people to see an exit during an emergency or power failure.

FINDING #2: Fire Safety

Applicable Regulations/Codes

- OSHA: Fire Protection (29 CFR 1910 Subpart L)
- NFPA: Portable Fire Extinguishers (NFPA 10)
- NFPA: National Fire Alarm and Signaling Code (NFPA 72)
- ICC International Fire Code, Chapter 6 Building Services and Systems

Summary

Site/Building	Location	Finding Description	Recommendation
Throughout	All buildings	High piled combustible material storage.	Stored material that is within 24 inches of ceiling height should be removed in non-sprinklered and 18 inches of ceiling height in sprinklered areas.
Throughout	All buildings	Fire extinguisher monthly inspection issues.	Perform and document (tag) monthly inspections and remove non-compliant units from service and replace as necessary.

Site/Building	Location	Finding Description	Recommendation
Throughout	All buildings	Mechanical and electrical rooms should be identified.	Place labels identifying mechanical/electrical rooms to assist in emergency incidents and fire department response.
Administrative Building	File Room	Fire extinguisher is out of annual inspection	Ensure extinguisher contractor completes annual inspection on all fire extinguishers.
Road Crew Work Area	Locker Room	Fire extinguisher is not mounted.	Ensure extinguishers are mounted in a position where they aren't blocked or impeding access to emergency equipment. Top of the extinguisher can be no more than 5 feet from the floor.
Throughout	Mechanical/Electrical Spaces or closets	Ensure ceiling penetrations have been fire stopped.	Ensure all penetrations in mechanical/electrical rooms have penetrations sealed with fire stop material.
Road Crew Work Area	Garages	Propane tanks stored inside the building.	Propane tanks should be stored outside if possible in a secured location.
Throughout	Mechanical/Electrical Spaces or closets	Electrical cabinets obstructed/blocked.	Remove any material blocking or impeding access to emergency equipment, such as sprinkler rooms, fire extinguishers etc.
Administrative Building	Rear Hallway Utility Closet	Combustible material stored by heat generating devices (tires).	Remove any combustible material from around any heat generating devices.
Road Crew Work Area	Garage	Portable outdoor gas-fired heating appliances used in doors.	Gas fueled heating sources intended for outdoor use may not be assembled or used inside of any occupancy.

FINDING #3: Flammable Liquid Storage

Applicable Regulations/Codes

- OSHA: Hazardous Materials (29 CFR 1910 Subpart H)
- NFPA: Life Safety Code (NFPA 101)
- NFPA: Fire Code (NFPA 1)
- International Fire Code, Chapter 34 Storage of Flammable and Combustible Liquids and Chapter 27 Hazardous Materials.

Summary

Site/Building	Location	Finding Description	Recommendation
Throughout	Maintenance/Work Areas	Flammable storage container not placed in storage cabinet.	Place all flammable storage containers in designated flammable storage cabinets.
Throughout	Maintenance/Work Areas	Installation of code complaint flammable storage cabinet.	All flammable/combustible liquids should be stored in a designed secured location that is adequately vented to the outside.
Road Crew Work Areas	Garage Areas	Flammable/combustible storage containers require spill control.	All flammable liquids having a capacity greater than 30 gallons and combustible liquids greater than 110 galls shall have spill control and secondary containment.

FINDING #4: Electrical Safety

Applicable Regulations/Codes

- OSHA: Electrical (29 CFR 1910 Subpart S)
- NFPA: National Electric Code (NFPA 70)

Summary

Site/Building	Location	Finding Description	Recommendation
Administrative Building	Staff Kitchen	Missing ground fault protection at water source.	Provide all electrical outlets within 6 feet of water sources with GFCI protection.
Administrative Building	Rear hallway Utility Closet	Missing ground fault protection at water source.	Provide all electrical outlets within 6 feet of water sources with GFCI protection.
Road Crew Work Area	South Garage	Electrical distribution box breakers are not all marked, identified or labeled.	Ensure that all circuit breakers are legibly marked or identified to clearly state what power is supplied to.

FINDING #5: Hazard Communication/Employee Right-to-Know

Applicable Regulations/Codes

- OSHA: Hazard Communications (29 CFR 1910.1200)
- PA DOLI: Pennsylvania Worker and Community Right to Know Act (Act 159 of 1984)

Summary

Site/Building	Location	Finding Description	Recommendation
All buildings	All areas where employees contact chemicals	Hazard Communication Training	OSHA has updated its Hazard Communications Standard with new Global integration information and all persons who come into contact required training by December 1, 2013. PA Department of Labor and Industry have recommended that all public sector employers comply with the OSHA Hazard Communication Standard.
All buildings	All MSDS locations	MSDS Issues	Maintain a current supply of MSDS sheets for all hazardous chemicals used on-site. MSDS should be readily available for each site and should contain an index. This should be updated regularly but no longer than annually.
All buildings	All MSDS locations	Hazardous Substance Survey Form (HSSF)	Complete and post the HSSF identifying on-site hazardous substances and update annually (by April 1). A copy should be available for PA DOLI review upon request
Throughout	All areas	Unlabeled secondary containers.	Ensure all chemical container labels on any storage container identifying the contents and any hazard information.

FINDING #6: Walking and Working Surfaces (Physical Hazards)

Applicable Regulations/Codes

- OSHA: Walking-Working Surfaces: Guarding Floor and Wall Openings (29 CFR 1910 Subpart D)
- OSHA: Safety Color Code for Marking Physical Hazards (29 CFR 1910.144)

Summary

Site/Building	Location	Finding Description	Recommendation
Road Crew Work Area	Garage/Mezzanine	Fabricated hand/guard rails are not strong enough to withstand 200 pounds of downward and outward force.	Remove or reinforce hand/guard rails to ensure adequate protection for personnel using stairs.
Throughout	All Buildings	Missing load rating identification.	Raised mezzanines or storage shelving are to be labeled with maximum rated load to prevent overburden.
Road Crew Work Area	Mezzanine Storage	Guard rail supporting signs or other heavy material.	Ensure storage of heavy objects still provides adequate employee fall protection.

FINDING #7: Storage Tank, Pressure Vessels and Compressed Gases

Applicable Regulations/Codes

- PA Department of Labor and Industry 34 PA Code 13
- American Society of Mechanical Engineers (ASME) Boiler and Pressure Vessel Code
- ICC International Fire Code, Chapter 30 Compressed Gases

Summary

Site/Building	Location	Finding Description	Recommendation
Road Crew Work Area	Garages	Any compressed gas cylinder is required to be secured.	Compressed gas cylinders are required to be secured in such a way to prevent tip over.
Road Crew Work Area	Garages	Compressed gas cylinders are not be protected from damage.	Gas cylinders are to be housed in such a way to prevent damage.
Road Crew Work Area	Garages	Ensure compressed gas cylinder valves are protected.	Gas cylinder valves are required to be protected from physical damage.

FINDING #8: Machine Guarding Deficiencies

Applicable Regulations/Codes

- OSHA: Machinery and Machine Guarding (29 CFR 1910 Subpart O)

Summary

Site/Building	Location	Finding Description	Recommendation
Road Crew Work Areas	Garages	Ensure all portable equipment with attached safety guards or shields are in place.	Ensure guards and shields are in-place and properly adjusted.

FINDING #9: General Housekeeping Items

Applicable Regulations/Codes

- OSHA: General Duty Clause (29 CFR 1910 Subpart A)

Summary

Site/Building	Location	Finding Description	Recommendation
Administrative Building	File Room, Reception Area, and Men's Room.	Water stained ceiling tiles	Repair all sources of water infiltration and removed damaged or degraded ceiling tiles.
Road Crew Work Areas	Office	Water stained ceiling tiles	Repair all sources of water infiltration and removed damaged or degraded ceiling tiles.
Outside	Fuel Tank and Dispensing Pump	Operating instructions for equipment.	Ensure basic instructions are available to ensure safe and efficient operation.
Outside	Fuel Tank and Dispensing Pump	Emergency instructions and contact information missing.	Ensure emergency instructions, including location of emergency stop (if equipped), location of spill control equipment and emergency notifications are noticeably posted.
Outside	Fuel Tank and Dispensing Pump	Spill control equipment.	Ensure an adequate supply of spill control material that is readily accessible and available in the event of a spill or leak.


CERTIFICATION:

The information contained in this report is believed to be accurate and true to the best knowledge of the inspector(s). Findings and recommendations for this investigation are based on the observations of the conditions, as they existed at that time. The inspector(s) and Cocciardi and Associates, Inc. assumes no liability for financial or health consequences due to actions or lack of actions taken by the client as a result of this inspection.

Sincerely,



Rocco DiPietro, CSP
Senior Principal
Cocciardi and Associates, Inc.



Jason W. Smith
Safety, Health and Environmental Technologist
Cocciardi and Associates, Inc.

cc: Michael Bartoletti, Safety Coordinator, HARIE
Diane Hollenbach, Township Manager, Maidencreek Township (via email)

File
Attachment

pennsylvania
DEPARTMENT OF LABOR & INDUSTRY
BUREAU OF WORKERS' COMPENSATION

EMPLOYEE WORKPLACE NOTICE PUBLIC SECTOR

Pennsylvania Worker and Community Right To Know Act

The Pennsylvania Worker and Community Right to Know Act requires that information about hazardous substances in the workplace and in the environment is available to public sector employees and employees of private sector workplaces not covered by the Federal Occupational Safety and Health Administration (OSHA) Hazard Communication Standard and to all persons living or working in the state. Employee rights listed below are further defined in the Worker and Community Right to Know Act (P.L. 734, No. 159) and Regulations. For additional information, contact the Department of Labor & Industry, Bureau of Workers' Compensation, Health & Safety Division, 1171 S. Cameron Street, Room 324, Harrisburg, Pennsylvania 17104-2501; Phone: 717-772-1635; Fax: 717-783-6365; E-mail: RA-LI-BWC-SAFETY@pa.gov.

Employee Workplace Notice:

Public sector employers (including state and local government agencies and public schools and public universities) and private sector employers not covered by the OSHA Hazard Communication Standard must post this notice informing employees of their rights under the law. This notice must be posted prominently in the workplace at a location where employee notices are normally posted.

Training:

Public sector employers and private sector employers not covered by the OSHA Hazard Communication Standard must provide an annual education and training program to employees exposed to hazardous substances. The training program may be presented either in written form or in training sessions.

Hazardous Substance Survey Form:

The Hazardous Substance Survey Form (HSSF) provides an inventory of the hazardous substances found in the workplace during the prior calendar year. All employers must complete a workplace HSSF annually. Public sector employers and private sector employers not covered by OSHA must post the HSSF prominently in the workplace and must provide a copy to any employee upon request.

Work Area List:

The Work Area List names the hazardous substances used or produced in a specific work area in the workplace. Public sector employers and private sector employers not covered by the OSHA Hazard Communication Standard must update a Work Area List at least annually, must provide a copy to any employee of the work area upon request, and must offer a copy to any employee newly assigned to that work area.

Material Safety Data Sheet/Safety Data Sheet:

The Material Safety Data Sheet (MSDS)/Safety Data Sheet (SDS) provides detailed information about a hazardous substance. In public sector workplaces and private sector workplaces not covered by the OSHA Hazard Communication Standard, an MSDS/SDS must be accessible in the work area where the hazardous substance it describes is used. MSDSs/SDS must be readily available to employees without the intervention or permission of management or supervisors, and any employee may obtain and examine an MSDS/SDS for any hazardous substance in the workplace. If an employee's request to obtain a copy of an MSDS/SDS is made to the employer in writing and, after five working days from the date the request is made, the employer fails to furnish the employee with an MSDS/SDS in the employer's possession or fails to provide the employee with proof of the employer's effort to obtain the requested MSDS/SDS from the manufacturer, importer, supplier or distributor and from the Department of Labor & Industry, the requesting employee may refuse to work with the substance.

Environmental Hazard Survey Form:

The Environmental Hazard Survey Form (EHSF) provides information about any environmental hazards emitted, discharged or disposed of from the workplace. All employers are required to complete an EHSF when and if requested to do so by the Department of Labor & Industry. If an EHSF has been completed by a public sector employer or a private sector employer not covered by the OSHA Hazard Communication Standard, a copy must be provided to any employee upon request.

Labeling:

All containers and ports of pipelines of hazardous and non-hazardous substances in public sector workplaces and private sector workplaces not covered by the OSHA Hazard Communication Standard must be properly labeled. Employers must ensure that each label, sign, placard or other operating instruction is prominently affixed and displayed on the container or port of a pipeline system so that employees can easily identify the contents.

Health and Exposure Records:

Public sector employers and private sector employers not covered by the OSHA Hazard Communication Standard must maintain and allow employee access to records of employee chemical exposure to the extent required by OSHA (under 29 CFR 1910.1200) or by the Mine Safety Health Administration (under 30 CFR 70.210 and 71.210).

Non-discrimination:

If a public sector employee or an employee of a private sector workplace not covered by the OSHA Hazard Communication Standard believes that he or she has been discharged, disciplined or discriminated against by an employer for exercising his or her rights granted under the Pennsylvania Worker and Community Right to Know Act, that employee has 180 days from the date of the alleged violation to file a written complaint with the Department of Labor & Industry, Bureau of Workers' Compensation, Health & Safety Division.

Auxiliary aids and services are available upon request to individuals with disabilities.
Equal Opportunity Employer/Program

Federal Communications Commission
Washington, DC 20554

Informational Notice of Section 106 Filings

Date: 02/25/2015
Reference Number: 851076

David Franke, Chair
Maidencreek Township Board of Supervisors
P.O. Box 289
Blandon, PA 19510

The following new Section 106 filing has been submitted:

FILE NUMBER: 0006676854
Purpose: New Tower Submission Packet
Notification Date: 7AM EST 02/20/2015
Applicant: Verizon Wireless
Consultant: Richard Grubb & Associates, Inc.
Positive Train Control Filing Subject to Expedited Treatment Under Program Comment: No
Site Name: RDG Evansville
Site Address: 220 Buena Vista Road
Detailed Description of Project: Verizon Wireless plans to lease a 50-foot by 50-foot area to construct a fenced telecommunications compound containing a proposed equipment shelter, stand-by generator, and monopole with an overall tower height of 130 feet.
Site Coordinates: 40-28-41.8 N, 075-53-09.7 W
City: Fleetwood
County: BERKS
State: PA
Lead SHPO/THPO: Pennsylvania Historical & Museum Commission Bureau for Historic Preservation

Consultant Contact Information:
Name: Jennifer Leynes
Title: Senior Architectural Historian
PO Box:
Address: 259 Prospect Plains Road
Building D
City: Cranbury
State: NJ
Zip: 08512
Phone: (609) 655-0692
Fax: (609) 655-3050
Email: jleynes@richardgrubb.com

NOTICE OF FRAUDULENT USE OF SYSTEM, ABUSE OF PASSWORD AND RELATED MISUSE

Use of the Section 106 system is intended to facilitate consultation under Section 106 of the National Historic Preservation Act and may contain information that is confidential, privileged or otherwise protected from disclosure under applicable laws. Any person having access to Section 106 information shall use it only for its intended purpose. Appropriate action will be taken with respect to any misuse of the system.

11TH DISTRICT
JUDITH L. SCHWANK

SENATE BOX 203011
HARRISBURG, PA 17120-3011
717-787-8925
FAX: 717-772-0578

210 GEORGE STREET
SUITE 201
READING, PA 19605
610-929-2151
FAX: 610-929-2576

EMAIL: senatorschwank@pasenate.com
WEBSITE: www.senatorschwank.com

Senate of Pennsylvania

COMMITTEES

AGRICULTURE & RURAL AFFAIRS, DEMOCRATIC CHAIR
AGING & YOUTH
APPROPRIATIONS
PUBLIC HEALTH & WELFARE
STATE GOVERNMENT
POLICY

AGRICULTURE ADVISORY BOARD
AGRICULTURE AND RURAL YOUTH DEVELOPMENT
ANIMAL HEALTH AND DIAGNOSTIC COMMISSION
STATE AGRICULTURAL LAND PRESERVATION BOARD

Harrisburg

March 3, 2015

Board of Supervisors
Maidencreek Township
PO Box 319
Blandon, PA 19510

Dear Misters Rudderow, Beaver and Franke:

Thank you for your letter expressing concern over the increasing costs of the statewide 9-1-1 system. I appreciate knowing your support for the modernization of the Public Safety Emergency Telephone Act to provide for a sustainable system.

This is a process that has been on-going and the Senate Veterans Affairs and Emegency Preparedness Committee recently held a hearing into the issue of how to change the law to address the issues posed by technological changes. The Act is due to expire at the end of June, after having been renewed for a year in 2014 to allow these issues to be worked out. It is my understanding that the final touches are expected to be in place to meet that deadline.

Again, thank you for sharing your concern with me. Please let me know whenever I can help.

Sincerely,

Judith L. Schwank
Senator – 11th District

JLS:C

Fleetwood Area School District

ADMINISTRATION OFFICE • 801 N. Richmond Street, Fleetwood, PA 19522-1031
Phone: 610-944-9598 • FAX: 610-944-9408 • E-mail: peaken@fleetwoodasd.k12.pa.us

February 23, 2015

Diane Hollenbach
Maidencreek Township Manager
1 Quarry Road
Blandon, PA 19510

Dear Mrs. Hollenbach,

The Board of School Directors of the Fleetwood Area School District is working with the Fleetwood Library on their desire to expand. Members of the Board have met with personnel from the library to discuss the possibility of leasing space at the Fleetwood Elementary School.

The Board recognizes the importance of the library to our community. As such, it is willing to work with the library to develop a mutually acceptable lease rate. An important factor in this conversation is the amount of financial support local municipalities can provide to the library to help with their expansion. We are suggesting you consider the value of the library to your community and communicate with the library board regarding the amount (and any increase) your community can provide to assists with the expansion. Hopefully we can all work together to support this important community resource.

Thank you for working with us and the library to help address the library's needs.

Sincerely,

Gary A. Reinert
Board President

Paul B. Eaken
Superintendent

per Stephanie - Library is no longer pursuing the El. school.

Dear Maidencreek township Building,

Thank you so much for the use of your facilities for my Gold Project. I was able to donate 100 caps, 30 bouffant caps and 100 crayon bags to the duPont Children's Hospital. Thank you so much!

Sincerely,
Jacqueline Carroll