Equipment Report 1-9-16 thru 2-5-16

1-11 Changed fuel filter on crack sealer (860.1hrs)

1-12 Replaced RH leaking brake line on 621B wheel loader
Replaced broken blade shield on Stihl TS400 demo saw

1-20 Repaired high and low beam plow lights on truck #6
Repaired plow lights on #2
Worked on #6 plow. Power angle not working

1-26 Replaced plow lift cyl. on truck #4, factory defect
Replaced brown hyd. line on #3 high pressure
Fixed air leak on #2, dash gauge leaking 10-20 psi per 3 minutes

2-1 Replaced thermostat in #7

2-3 Pressure washed #1 and #2
Called PowerCo about 621B full service and mini service

2-4 Replaced plow springs on #2 plow
Prepped and put first coat on #3 dumpbody
Fixed forks

2-5 Finished #3 body and painted #2 plow
Replaced tool box on #2
Replaced corroded battery cable on 621B and replaced rotten tie downs for batteries