Equipment Report 2-6-16 thru 3-4-16

2/8

Greased all equipment (AL & BW)

C 5500	26,730mi	
F750	8,458.2 mi	707hrs
Backhoe	2,220hrs	
C8500	28,315mi	
621B	1,180hrs	
F550	6,736.1mi	

2/9

#3 Compressor Relay (AL & BW)

#4 Spreader direct line hookup (AL & BW)

2/10

Adjusted plow headlights and beacon light on truck #3 (BW)

Fixed parking brake on 621B (AL)

2/11

Installed radio filter in truck #5 (AL & BW)

Patched tire chains back together for trucks #1 & #2 (AL & BW)

2/12

Fixed all truck tire chains

Aimed truck #7 plow lights & tilted cutting edge

Plugged front tire on truck #7 (AL & BW)

2/15

Welded cracks on truck #6 plow frame & aimed truck #6 plow light (AL & BW)

2/16

Replaced bad wire harness on truck #6 plow

Installed new cylinder pins on truck #4 lift cylinder

2/17

Replaced and upgraded work lights on trucks #2, #3 & #6 (AL & BW)

Made new spinner shield (AL & BW)

2/19

Tightened cylinder packings on #5 plow

2/23

Switched radio in truck #4 (BW)

Started installing radio in backhoe (AL & BW)

2/24

Finished installing radio in backhoe (AL & BW)

Installed radio in truck #8 (AL & BW)

Changed out antenna on truck #4 (AL & BW)

2/25

PowerCo serviced mini-ex

2/29

Blew out and went over demo saw