OS-2 (12-15)

pennsylvania
DEPARTMENT OF TRANSPORTATION

March 1, 2016

Ms. Diane E. Hollenbach, Manager
Maidencreek Township
PO Box 319
Blandon, PA 19510

Re: Berks–Maidencreek Township–SR 222 & Tamarack Boulevard/Genesis Drive

Dear Ms. Hollenbach:

The Traffic Signal Condition Diagram for the above referenced intersection has been modified to reflect the revised pedestrian timings. The revised times have been implemented by your Traffic Signal Maintenance Contractor during a recent maintenance visit. As a result of this revisions, no further physical work is required.

We have enclosed the revised Traffic Signal Condition Diagram for Permit Number 06-222-004. Please have the appropriate Township official sign and return the mylar to this office. Once the signed mylar is received, we will issue the revised Traffic Signal Permit.

Should you have any questions, please contact Adam D. Stettler at 610.871.4480.

Sincerely,

Christopher J. Surovy
District Traffic Signals Manager
Engineering District 5-0

Enclosure

cc: Mr. John Hivner
TELCO, Inc.
1224 Cross Keys Road
Reading PA 19605