Equipment Report 8-6-16 thru 9-2-16

8/18

Replaced motor on air compressor and serviced air compressor

Fixed failed emissions code and massive EVAP leak on truck #7

Sharpened all blades on all mowers and detailed Kubota zero turn

8/22

Picked up Exmark Lazer Z S-series for warranty work

8/23

Took Exmark Lazer S-series mower deck off and pressure washed it.

Fixed bent mower deck and cracked spindle on Exmark Lazer S-series

8/24

Straightened mower deck and replaced spindle, hub and pulley

Put Lazer Z S-series back together.

Replaced tanks and grommets on pole saw

8/25

Replaced drive belt on Exmark Lazer Z S-series

Adjusted parking brake on Exmark XP

8/31

Replaced water pump, upper & lower radiator hoses, replaced serpentine belt, replaced AC belt, checked tires and greased – truck #8

9/1

Replaced faulty switches on old big gas mower, greased and inspected