PO #: Account #: Date: Tue Mar 6 2018

Dealer Information		Customer Information	
Name:	DEER COUNTRY FARM AND LAWN	Name:	MAIDENCREEK TOWNSHIP
Address:	ADAMSTOWN, PA 19501 United States	Address:	MAIDENCREEK TOWNSHIP
Phone:	7174844391	Phone:	
Fax:	n/a	Email:	
Contact:		Contact:	

Vehicle Information

PIN: Vehicle: Agriculture > TRACTOR > 5510 - TRACTOR > 5210, 5310, 5410 and 5510 Tractors (North America Edition) (PC2615)

Part No.	Description			Qty	Unit Price	Price
R111173	ISOLATOR	Agriculture	5510 - TRACTOR	1	25.19	25.19
R66375	ISOLATOR	Agriculture	5510 - TRACTOR	1	24.21	24.21
R134				6	6.50	39.00
SWJHD1130	RADIO			1	160.36	160.36
RE67675	SPEAKER	Agriculture	5510 - TRACTOR	2	35.01	70.02
R113854	SPRING	Agriculture	5510 - TRACTOR	1	17.04	17.04
R79605	WASHER			4	2.65	10.60
SE500826	INJECTION NOZZLE REMAN	Agriculture	5510 - TRACTOR	4	82.26	329.04
RE232258	INSTRUMENT CLUSTER			1	576.58	576.58
RE42470	SWITCH	Agriculture	5510 - TRACTOR	1	34.72	34.72
R132455	CYLINDER	Agriculture	5510 - TRACTOR	1	82.95	82.95
R117721	CLAMP	Agriculture	5510 - TRACTOR	4	2.82	11.28
TY22328	BULK HOSE			10	1.01	10.10
R129970	ROOF	Agriculture	5510 - TRACTOR	1	835.85	835.85
A4730R	O-RING	Agriculture	5510 - TRACTOR	2	1.96	3.92
L56974	HOSE FITTING	Agriculture	5510 - TRACTOR	2	4.13	8.26
R139015	HYDRAULIC HOSE	Agriculture	5510 - TRACTOR	1	14.00	14.00

Currency:			Shop	Subtotal:	2253.12
Labor Hours:	30	Labor Rate:	85	Labor:	2550.00
		Shipping Method:	Road	Shipping:	
				Tax:	
			95	**Total:**	**4803.12**

See attached paper for rates

Copyright © 2018 Deere & Company. All Rights Reserved.

MAIDENCREEK TOWNSHIP

-Brake valve over flow fitting is leaking oil

-Door shock doesnt hold door open

-Fuel guage needle is broke, reconmend new dash- will reset hours to "0"

-Engine smokes white, reconmend replacing injectors

-Pto light in dash doesnt work

-Pto shaft drags when not turned on

-Radio doesnt work or the speakers are broken.

-Ac needs recharged.

-Hydraulic oil leak at scv valve, have to wash off.

-Heater hoses under cab are bad because hyd oil was leaking on them.

-Rear lh cab mount needs replaced.

-Roof is all crakced and broken, leaks water in.

-Change oil in front mfwd hubs.

AG
Shop Labor Rate $85.00 per hr.
-
Field Labor Rate $95.00 per hr. + $1.50 per mi.

p/u / delivery

259.00